

APPENDIX VII

FIRE SAFETY CERTIFICATE

NO: 05/2021

DATED:13.01.2021

Certified that the **OM SHANTHI HIGHER SECONDARY SCHOOL (CBSE)**,
S.F.NO: 167/7B2, THADICOMBU ROAD, KURUMBAPATTI VILLAGE & PANCHAYAT, DINDIGUL TALUK, DINDIGUL DISTRICT. comprised of Ground floor (basements) and First and second floor (upper floors) owned by **OM SHANTHI HIGHER SECONDARY SCHOOL (CBSE)** have complied with the fire prevention and fire safety requirements in accordance with rule of state/UT Fire service Rules, and verified by the officers concerned of Fire Service on **13.01.2021** (date of inspection) in the presence of **Mr.K.SAKTHIVEL** Station Officer, Fire and Rescue Station, Dindigul and that the building/premises is fit for occupancy class **SCHOOL BUILDING- ALL CLASS ROOM'S AND OFFICE ROOM'S** with **effect from 12/01/2022** for a **period of One year** in accordance with rule and subject to compliance of the conditions.

Issued on 13/01/2021 at Dindigul by




STATION OFFICER
FIRE AND RESCUE STATION
DINDIGUL.

Signature with seal

Name : K.SAKTHIVEL

Designation : Station Office

To,

THE CORRESPONDENT,
OM SHANTHI HIGHER SECONDARY SCHOOL (CBSE),
S.F.NO: 167/7B2, THADICOMBU ROAD,
KURUMBAPATTI VILLAGE & PANCHAYAT,
DINDIGUL TALUK,
DINDIGUL DISTRICT.

Copy To: District Officer, Fire and Rescue Service, Dindigul.